

<b>Observation Number:</b>	202029319
<b>Originator:</b>	
<b>Date Created:</b>	17-Jun-2020
<b>Business Unit:</b>	Asset Solutions Americas
<b>Business Group:</b>	Capital Projects Power Process & Energy
<b>Project/Office:</b>	Lincoln County CT Project
<b>Service Line:</b>	EPC Industrial
<b>Site/Office Name:</b>	Lincoln County CT Project
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Fuel Oil Tank
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Shanice Kirkland
<b>Observer Email Address:</b>	katie.schroeder2@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	06-Jun-2020
<b>Observation Time:</b>	09:30
<b>Observation Close Date:</b>	17-Jun-2020
<b>Observation Category:</b>	Contractor Site safety Safety awareness & behaviour
<b>Name of Individual or Team:</b>	Pipe Crew
<b>Details of safety observation:</b>	Before starting a pipe test the crew makes sure there is no one in the area and that the barricade is properly established.
<b>Immediate action taken:</b>	
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No