

Observation Number:	201928775
Originator:	
Date Created:	25-Oct-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Automation & Control
Project/Office:	Houston Process
Service Line:	Process North America
Site/Office Name:	Houston Process - Other Clients
Home or Work Related Observation?:	Home
Exact Location or Project of Act/Condition/Safe Behaviour:	Home garage
Observation Type:	Unsafe Condition
Observer Name:	Jason Norris
Observer Email Address:	JNorris@Marathonpetroleum.com
Stakeholder:	Client
Observation Date:	12-Oct-2019
Observation Time:	13:00
Observation Close Date:	25-Oct-2019
Observation Category:	Travel and Safety away from the office Transportation
Details of safety observation:	I was in the garage cleaning out my vehicle and noticed a nail in my front tire. The tire was still holding air but this could have resulted in the tire going flat on my commute.
Immediate action taken:	Immediately took the vehicle to the automotive shop to have the tire repaired.
Supporting Information:	
Feedback required?:	No