

Observation Number:	201810257
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Dukestown Rd Tredegar
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	26-Mar-2018
Observation Time:	08:45
Observation Close Date:	18-Jul-2018
Details of safety observation:	Traffic Lights attempted to be stolen - Damage to Lock and clamp
Immediate action taken:	Team arranged with hire company to replace lock and clamp
Supporting Information:	
Feedback required?:	No