

<b>Observation Number:</b>	201925124
<b>Originator:</b>	
<b>Date Created:</b>	20-Sep-2019
<b>Business Unit:</b>	TCS
<b>Business Group:</b>	Mining & Minerals
<b>Project/Office:</b>	Kemerton Project
<b>Service Line:</b>	APAC
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Main Office complex
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	19-Sep-2019
<b>Observation Time:</b>	10:00
<b>Observation Close Date:</b>	22-Sep-2019
<b>Observation Category:</b>	Procedures and Instructions Followed / Not Followed
<b>Details of safety observation:</b>	On walking out to site using designated walkways, I observed contractor employees returning for morning break not using the designated green flagged walk way
<b>Immediate action taken:</b>	Stopped group and highlighted the reason we have green flagged walkways is to keep pedestrians segregated from traffic areas
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No