

Observation Number:	202231141
Originator:	
Date Created:	11-May-2022
Business Unit:	Operations
Business Group:	Americas
Project/Office:	O&M South (C&M) – ExxonMobil
Sub Business Group:	US South
Site/Office Name:	Exxon Baytown BOP
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	BOP-BD
Observation Type:	Safe Behaviour
Observer Name:	LUIS GUERRERO
Observer Email Address:	LUIS.GUERRERO@EXXONMOBIL.COM
Stakeholder:	Wood
Observation Date:	09-May-2022
Observation Time:	01:00
Observation Close Date:	11-May-2022
Observation Category:	Procedures and Instructions Followed / Not Followed
Name of Individual or Team:	MAINTENANCE
Details of safety observation:	Workers performing a hydro test, followed procedure by barricading the area, wearing proper PPE and not allowing anyone who doesn't need to be in the area in.
Immediate action taken:	Followed procedure as written
Supporting Information:	
Feedback required?:	No