

Observation Number:	202229407
Originator:	
Date Created:	03-May-2022
Business Unit:	Operations
Business Group:	Americas
Project/Office:	O&M South (C&M) – ExxonMobil
Sub Business Group:	US South
Site/Office Name:	Exxon Baytown BOP
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	BOP2X
Observation Type:	Safe Behaviour
Observer Name:	Luis Guerrero
Observer Email Address:	luisguerrero1109@gmail.com
Stakeholder:	Wood
Observation Date:	02-May-2022
Observation Time:	02:00
Observation Close Date:	03-May-2022
Observation Category:	Contractor Site safety Personal Protective Equipment
Name of Individual or Team:	Maintenance
Details of safety observation:	Crew was working on putting an exchange back together, one important PPE to remember was to put on goggles because it was a caustic area. Its easy to move in and out and forget to put them on but all the crew did as needed without fail.
Immediate action taken:	Correct action was taken and everyone was safe
Supporting Information:	
Feedback required?:	No