

<b>Originator:</b>	
<b>Date Created:</b>	26-Feb-2019
<b>Business Unit:</b>	E&I Solutions
<b>Business Group:</b>	Canada
<b>Project/Office:</b>	Canada - West
<b>Site/Office Name:</b>	Edmonton, AB
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	One step off the carpet from the main floor back entrance
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Natalie Tremblay
<b>Observer Email Address:</b>	natalie.tremblay@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	11-Feb-2019
<b>Observation Time:</b>	10:30
<b>Observation Close Date:</b>	26-Feb-2019
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)
<b>Details of safety observation:</b>	I stepped off the mat onto the polished concrete and slipped. I caught myself before I fell but was not impressed with the lack of carpet/polished floor.
<b>Immediate action taken:</b>	Told Tim Kihn
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No