

Observation Number:	201808425
Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Primrose Bank, Bushcombe Lane, GL52 4QQ
Observation Type:	Unsafe Condition
Observer Name:	Chris Cornes
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	16-Jan-2018
Observation Time:	08:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	Leading arrows down by the barriers.
Immediate action taken:	Chris put sandbags to weigh back down, to make site safe and secure.
Supporting Information:	
Feedback required?:	No