

Observation Number:	201902055
Originator:	
Date Created:	12-Feb-2019
Business Unit:	E&I Solutions
Business Group:	Western US
Project/Office:	United States - West
Site/Office Name:	Carlsbad Brine Well Remediation
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Drill rig floor
Observation Type:	Safe Behaviour
Observer Name:	Matthew Magill
Observer Email Address:	matthew.magill@woodplc.com
Stakeholder:	Wood
Observation Date:	09-Feb-2019
Observation Time:	07:30
Observation Close Date:	12-Feb-2019
Observation Category:	Contractor Site safety Personal Protective Equipment
Name of Individual or Team:	Boart Longyear Coring Division
Details of safety observation:	Driller's hand was wearing impact gloves when tripping in drill rods to prevent injury from pinched fingers.
Immediate action taken:	n/a
Supporting Information:	
Feedback required?:	No