

<b>Observation Number:</b>	201925125
<b>Originator:</b>	
<b>Date Created:</b>	20-Sep-2019
<b>Business Unit:</b>	Specialist Technical Solutions
<b>Business Group:</b>	Mining & Minerals
<b>Project/Office:</b>	Kemerton Project
<b>Service Line:</b>	Australia
<b>Site/Office Name:</b>	Albemarle
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	SMP laydown area
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	3rd Party
<b>Observation Date:</b>	20-Sep-2019
<b>Observation Time:</b>	14:30
<b>Observation Close Date:</b>	20-Sep-2019
<b>Observation Category:</b>	Integrity Management Competence
<b>Name of Individual or Team:</b>	SMS Scaffolding
<b>Details of safety observation:</b>	Observed scaffolder's building tank scaffold, task was done in a safe and competent manner everything in place task was discussed between all parties and grounds for erecting agreed on a practical basis .
<b>Immediate action taken:</b>	Observed for some time congratulated on task well done
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No