

<b>Observation Number:</b>	202225492
<b>Originator:</b>	
<b>Date Created:</b>	14-Apr-2022
<b>Business Unit:</b>	Operations
<b>Business Group:</b>	Americas
<b>Project/Office:</b>	O&M South (C&M) – ExxonMobil
<b>Sub Business Group:</b>	US South
<b>Site/Office Name:</b>	Exxon Baytown BOP
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Train 2
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Luis Guerrero
<b>Observer Email Address:</b>	luisguerrero1109@gmail.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	14-Apr-2022
<b>Observation Time:</b>	01:00
<b>Observation Close Date:</b>	14-Apr-2022
<b>Observation Category:</b>	Travel and Safety away from the office Falls and Slips
<b>Name of Individual or Team:</b>	Projects
<b>Details of safety observation:</b>	When needing to get to the job site that was located on top of a platform, the worker had to climb a caged ladder. Upon reaching the ladder he secured all loose objects and climbed using 3 points of contact the entire time up.
<b>Immediate action taken:</b>	Correct action was taken, 3 points of contact and did not rush to get to the top
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No