

Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Stevens Road, Prestatyn
Observation Type:	Unsafe Condition
Observer Name:	Paul Williams
Observer Email Address:	paul.astley@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	13-Feb-2018
Observation Time:	10:30
Observation Close Date:	18-Jul-2018
Details of safety observation:	20ml House entries - valves to turn up and down are jammed.
Immediate action taken:	Team leader has given the 2 valves to Mark Morris.
Supporting Information:	
Feedback required?:	No