

Originator:	
Date Created:	11-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	lougher place, bridgend
Observation Type:	Unsafe Condition
Observer Name:	Jeremy Hill
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	01-Feb-2018
Observation Time:	14:00
Observation Close Date:	
Details of safety observation:	ISL:team turned up to reinstate sch 4 works 6000395323, no protection left to protect excavation
Immediate action taken:	team reinstaeted concrete patch in rapid set, touch dry in around 15mins before they left.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related