

<b>Originator:</b>	
<b>Date Created:</b>	24-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Cliff Terrace Burryport
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Joe Smiriglia
<b>Observer Email Address:</b>	steve.edwards@wwutilities.co.uk
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	18-Jul-2018
<b>Observation Time:</b>	09:30
<b>Observation Close Date:</b>	03-Oct-2018
<b>Details of safety observation:</b>	The team cannot get hold of the print out data on the Butt Fusion machine
<b>Immediate action taken:</b>	Steve Edwards will contact PSS
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Action to be taken:</b>	Escalated with the project as a quality/supply chain issue
<b>Comments from OU Admin</b>	
<b>Closing Comments:</b>	Passed to project to manage locally given the contractual changes