

Observation Number:	201900776
Originator:	
Date Created:	21-Jan-2019
Business Unit:	AS EAAA
Business Group:	Capital Projects EAAA
Project/Office:	Shell Bukom EFA Projects
Service Line:	Asia Pac
Site/Office Name:	Shell Bukom
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	TGU area under pipe rack
Observation Type:	Safe Condition
Observer Name:	Reddy Ashok Vellappa
Observer Email Address:	Ashok.reddy@woodplc.com
Stakeholder:	Contractor
Observation Date:	03-Jan-2019
Observation Time:	02:45
Observation Close Date:	21-Jan-2019
Observation Category:	Contractor Site safety Signage and instructions
Details of safety observation:	All Scaffold tagging and instruction are clear to use it some place required H2S Mask Provided around that area its very use full to claim up and checking and site survey
Immediate action taken:	
Supporting Information:	
Feedback required?:	No