

| | |
|---|---|
| Originator: | |
| Date Created: | 16-Jul-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Stevens Road, Prestatyn |
| Observation Type: | Unsafe Condition |
| Observer Name: | Paul Williams |
| Observer Email Address: | paul.astley@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 13-Feb-2018 |
| Observation Time: | 10:30 |
| Observation Close Date: | 18-Jul-2018 |
| Details of safety observation: | 20ml House entries - valves to turn up and down are jammed. |
| Immediate action taken: | Team leader has given the 2 valves to Mark Morris. |
| Supporting Information: | |
| Feedback required?: | No |