

<b>Observation Number:</b>	201927482
<b>Originator:</b>	
<b>Date Created:</b>	14-Oct-2019
<b>Business Unit:</b>	E&I Solutions
<b>Business Group:</b>	Eastern US & Latin America
<b>Project/Office:</b>	United States - East
<b>Site/Office Name:</b>	Lisle, IL
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	C&D Technologies, Milwaukee,, WI. Assembly area, product storage area
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Lee Felski
<b>Observer Email Address:</b>	lee.felski@woodplc.com
<b>Stakeholder:</b>	Client
<b>Observation Date:</b>	08-Oct-2019
<b>Observation Time:</b>	15:00
<b>Observation Close Date:</b>	14-Oct-2019
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)
<b>Details of safety observation:</b>	While performing asbestos inspection, nearly walked into a large piece of wire that had unraveled from the palletted product storage area. the wire was from the fencing that sections off each pallet. There were many of these wires sticking out, likely caused by forklift truck damage.
<b>Immediate action taken:</b>	Bent as many as possible out of the way. Please note- This Inspection was for a company/factory shutdown/relocation, during the last final days of run time.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Reasons for Amendment</b>	
<b>Comment</b>	<b>Entered By</b>
<b>Date Entered</b>	
Additional info	14-October-2019 16:28