

Originator:	
Date Created:	30-May-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Wood temporary site office managed by BGC
Observation Type:	Unsafe Condition
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	30-May-2019
Observation Time:	06:00
Observation Close Date:	30-May-2019
Observation Category:	Work Environment Lighting & Noise
Details of safety observation:	Lack of light between site offices
Immediate action taken:	Reported to HSSE
Supporting Information:	
Feedback required?:	Yes
Comments from Reviewer	
Closing Comments:	BGC to install a floodlight between offices.