

Observation Number:	201810051
Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Clifford Av Kingsteignton
Observation Type:	Unsafe Act
Observer Name:	Jason Miller
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Feb-2018
Observation Time:	09:15
Observation Close Date:	
Details of safety observation:	Team were about to dispense at 125mm coil pipe off the trailer - None of the team have Coil Pipe Traler Training
Immediate action taken:	Jason Miller was on site doing an RO audit - and was able to assist has he got the "Coil Pipe Traler Training " . A suggestion has been raised forgoing forward for team members to that this training ???
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related