

<b>Observation Number:</b>	201809252
<b>Originator:</b>	
<b>Date Created:</b>	03-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Paganel Road, Minehead
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Nick Hartley
<b>Observer Email Address:</b>	trevor.clark@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	21-Jan-2018
<b>Observation Time:</b>	14:00
<b>Observation Close Date:</b>	
<b>Details of safety observation:</b>	CJ Lynch : Screw to hold down footboard to footpath had been left sticking out of the bottom of the board. When nick was loading the van to clear site, the screw caught his shirt and ripped it.
<b>Immediate action taken:</b>	Team removed screw from board to prevent anyone else catching it. Claw hammers have been issued for teams to remove any screws from boards.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Cancel Comments:</b>	Not a Wood observation