

Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	7 Jackson Close, Oxford
Observation Type:	Unsafe Condition
Observer Name:	Andy Lock
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Contractor
Observation Date:	09-Feb-2018
Observation Time:	09:00
Observation Close Date:	
Details of safety observation:	Complete Utilities :Team pulled up onsite to do reinstatement 2 of the barriers were down.
Immediate action taken:	Andy put sandbags back on signs and barriers back on and rectified the situation.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related