

Observation Number:	202027449
Originator:	
Date Created:	08-Jun-2020
Business Unit:	Asset Solutions Americas
Business Group:	Capital Projects Power Process & Energy
Project/Office:	Lincoln County CT Project
Service Line:	EPC Industrial
Site/Office Name:	Lincoln County CT Project
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	West Side of Stack
Observation Type:	Unsafe Act
Observer Name:	Ralph Nichols
Observer Email Address:	katie.schroeder2@woodplc.com
Stakeholder:	Wood
Observation Date:	02-Jun-2020
Observation Time:	09:45
Observation Close Date:	08-Jun-2020
Observation Category:	Contractor Site safety Personal Protective Equipment
Details of safety observation:	Employee driving a buggy with out their seatbelt on.
Immediate action taken:	Stopped employee and told them to put their seat belt on and they did.
Supporting Information:	
Feedback required?:	No