

Observation Number:	201808465
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	2 Southway Trowbridge Wiltshire
Observation Type:	Unsafe Condition
Observer Name:	Richard Llewlyn
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	18-Jan-2018
Observation Time:	08:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	Complete Utilities : Team turned up on site this morning to remove spoil. The spoil was not barrierd of or signed, due to high winds and weather conditions all signs / barriers around the spoil had blown around the site
Immediate action taken:	Before the team stated work the yeam replaced the barriers and signs and collected the spoil and made the site safe
Supporting Information:	
Feedback required?:	No