

Originator:	
Date Created:	09-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Hamlin Lane Exeter
Observation Type:	Unsafe Act
Observer Name:	Matt Raasch-sotinwa
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	29-Jan-2018
Observation Time:	13:30
Observation Close Date:	
Details of safety observation:	Daniel Mellor team member was seen driving the dumper without wearing a seatbelt .The T/L explained to Matt that he had set off on his journey wearing a seat belt , but was seen by Matt not wearing a seat belt on the return journey
Immediate action taken:	Matt explained to both the T/L and team member this is un acceptable and told the T/L to be more vigilant. He also did a TBT on site . The team member DM had only just received his dumper ticket in the last couple of weeks
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related