

Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Park View , Brynmawr
Observation Type:	Unsafe Condition
Observer Name:	James Osborne
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	02-May-2018
Observation Time:	08:15
Observation Close Date:	12-Sep-2018
Details of safety observation:	Overnight part of connection excavation has become unstable (previously deemed stable via RAMS) and fallen into excavation and onto gas main . No damage
Immediate action taken:	FLM instructed team to make safe , re - view RAMS form and batter back excavation
Supporting Information:	
Feedback required?:	No