

Observation Number:	201810252
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Park drive crickhowell
Observation Type:	Unsafe Act
Observer Name:	James Osborne
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	12-Mar-2018
Observation Time:	14:15
Observation Close Date:	18-Jul-2018
Details of safety observation:	Team using a 75 mil / 32 ml top tee when the nipple snapped off the top tee
Immediate action taken:	The team replaced with a new fitting
Supporting Information:	
Feedback required?:	No