

<b>Observation Number:</b>	201900844
<b>Originator:</b>	
<b>Date Created:</b>	21-Jan-2019
<b>Business Unit:</b>	Consulting
<b>Business Group:</b>	Applied Intelligence
<b>Project/Office:</b>	Houston AI
<b>Sub Business Group:</b>	Americas
<b>Site/Office Name:</b>	Houston AI - ExxonMobil
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	ISBL trailer parking lot
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Bukowski, Ed (WG Mustang)
<b>Observer Email Address:</b>	ed.bukowski@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	21-Jan-2019
<b>Observation Time:</b>	06:15
<b>Observation Close Date:</b>	21-Jan-2019
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)
<b>Details of safety observation:</b>	Parking lot was muddy.
<b>Immediate action taken:</b>	Walked down the row of cars until I found a safe place to walk. Then I spoke to the area owner and suggested additional stone in the area of the mud.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No