

Observation Number:	202226112
Originator:	
Date Created:	19-Apr-2022
Business Unit:	Operations
Business Group:	Americas
Project/Office:	O&M South (C&M) – ExxonMobil
Sub Business Group:	US South
Site/Office Name:	Exxon Baytown BOP
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Train 2
Observation Type:	Safe Behaviour
Observer Name:	Luis Guerrero
Observer Email Address:	luisguerrero1109@gmail.com
Stakeholder:	Wood
Observation Date:	19-Apr-2022
Observation Time:	02:00
Observation Close Date:	19-Apr-2022
Observation Category:	Travel and Safety away from the office Tools and Equipment
Name of Individual or Team:	Majors
Details of safety observation:	The job was completed on a platform and so the workers needed to bring their tools down, they loaded them up in an approved bag to prevent anything from falling out. Another worker was down below as the one on top lowered the bag to ensure no one walking by would be in the line of fire.
Immediate action taken:	Proper handling of tools and safety was applied here.
Supporting Information:	
Feedback required?:	No