

Observation Number:	202232825
Originator:	
Date Created:	19-May-2022
Business Unit:	Operations
Business Group:	Americas
Project/Office:	O&M South (C&M) – ExxonMobil
Sub Business Group:	US South
Site/Office Name:	Exxon Baytown BOP
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Fabrication Shop
Observation Type:	Safe Condition
Observer Name:	Luis Guerrero
Observer Email Address:	Luis.guerrero@exxonmobil.com
Stakeholder:	Wood
Observation Date:	16-May-2022
Observation Time:	03:00
Observation Close Date:	19-May-2022
Observation Category:	Work Environment Safe Distancing
Details of safety observation:	1.) Workers were performing a hydro test on a welded spool, took all safety measures of barricading off area, wearing proper PPE and alerting oncoming traffic to avoid the area. When pressure was released, proper PPE was updated to reflect the change in situation.
Immediate action taken:	Proper PPE and awareness was shown, workers did as needed to ensure the safety of themselves and others.
Supporting Information:	
Feedback required?:	No