

|   |  |
|---|--|
| <b>Observation Number:</b>  | 201925125  |
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 20-Sep-2019  |
| <b>Business Unit:</b>   | TCS  |
| <b>Business Group:</b>  | Mining & Minerals  |
| <b>Project/Office:</b>  | Kemerton Project   |
| <b>Service Line:</b>  | APAC   |
| <b>Site/Office Name:</b>  | Kemerton Project Site  |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | SMP laydown area   |
| <b>Observation Type:</b>  | Safe Behaviour   |
| <b>Observer Name:</b>   | Stephen Andrews  |
| <b>Observer Email Address:</b>                                    | steve.andrews3@woodplc.com   |
| <b>Stakeholder:</b>   | 3rd Party  |
| <b>Observation Date:</b>  | 20-Sep-2019  |
| <b>Observation Time:</b>  | 14:30  |
| <b>Observation Close Date:</b>                                    | 20-Sep-2019  |
| <b>Observation Category:</b>                                      | Integrity Management<br>Competence   |
| <b>Name of Individual or Team:</b>                                | SMS Scaffolding  |
| <b>Details of safety observation:</b>                             | Observed scaffolder's building tank scaffold, task was done in a safe and competent manner everything in place task was discussed between all parties and grounds for erecting agreed on a practical basis . |
| <b>Immediate action taken:</b>                                    | Observed for some time congratulated on task well done   |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | No   |