

Observation Number:	201810049
Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	61 Gadlys Street, Aberdare
Observation Type:	Unsafe Condition
Observer Name:	Dai Bailey
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Feb-2018
Observation Time:	08:15
Observation Close Date:	18-Jul-2018
Details of safety observation:	All signs and barriers were blown over
Immediate action taken:	Dai picked all the barriers back up and made site safe and secure
Supporting Information:	
Feedback required?:	No