

<b>Observation Number:</b>	201809625
<b>Originator:</b>	
<b>Date Created:</b>	09-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Hamlin Lane Exeter
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Matt Raasch-sotinwa
<b>Observer Email Address:</b>	john.dowson@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	29-Jan-2018
<b>Observation Time:</b>	13:30
<b>Observation Close Date:</b>	
<b>Details of safety observation:</b>	Daniel Mellor team member was seen driving the dumper without wearing a seatbelt .The T/L explained to Matt that he had set off on his journey wearing a seat belt , but was seen by Matt not wearing a seat belt on the return journey
<b>Immediate action taken:</b>	Matt explained to both the T/L and team member this is un acceptable and told the T/L to be more vigilant. He also did a TBT on site . The team member DM had only just received his dumper ticket in the last couple of weeks
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Cancel Comments:</b>	Not Wood related