

<b>Observation Number:</b>	201905149
<b>Originator:</b>	
<b>Date Created:</b>	21-Mar-2019
<b>Business Unit:</b>	Consulting
<b>Business Group:</b>	Applied Intelligence
<b>Project/Office:</b>	Houston AI
<b>Sub Business Group:</b>	Americas
<b>Site/Office Name:</b>	Houston AI - ExxonMobil
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	At height (160') in Vent/Gas Recovery unit
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Cliff McDonald
<b>Observer Email Address:</b>	Clifford.McDonald@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	18-Mar-2019
<b>Observation Time:</b>	10:00
<b>Observation Close Date:</b>	21-Mar-2019
<b>Observation Category:</b>	Contractor Site safety Procedure implementation
<b>Name of Individual or Team:</b>	Zachry
<b>Details of safety observation:</b>	While working at height in the Purification area, I was approached by a Zachry Foreman and asked about the inspection color on my fall protection. He was under the impression that Wood used the Zachry color code for quarterly inspections and I had to make a call to clear the matter up to his satisfaction. After informing him that Wood used the Exxon regular plant's color code scheme, he was satisfied and apologized for interrupting my work. I thanked him for his alertness and safe behavior and assured him that I was not offended by his action in any manner.
<b>Immediate action taken:</b>	Immediately stopped work to confirm that my fall protection was properly inspected. Commended the contractor for stopping me to ask about it. Discussed the event at the following morning's tool box safety meeting.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No