

Observation Number:	201913505
Originator:	
Date Created:	19-Jun-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Main common trench HV Sub
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	19-Jun-2019
Observation Time:	13:30
Observation Close Date:	19-Jun-2019
Observation Category:	Contractor Site safety Procedure implementation
Name of Individual or Team:	Nilsen eletrical
Details of safety observation:	Observed Nilsen Electrical setting up to winch cables from drum through excavated trench 500meters, set up was supervised by BGC all procedures and barricades were in place and tagged with relevant information, communication between winch operator and drum operator were clear and understandable time was taken in the execution of task to ensure every thing was covered.
Immediate action taken:	Congratulated team on job well done and encouraged them to keep up the good skills they had introduced .
Supporting Information:	
Feedback required?:	No