

<b>Observation Number:</b>	201601108
<b>Originator:</b>	
<b>Date Created:</b>	21-Mar-2016
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	EPC2 Antwerp
<b>Service Line:</b>	SERC
<b>Site/Office Name:</b>	EPC2 Antwerp - Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Antwerp Refinery, Laan P
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Cristian Loi
<b>Observer Email Address:</b>	TIOTIE.ExxonmobilAntwerp@fwceu.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	21-Mar-2016
<b>Observation Time:</b>	09:15
<b>Observation Close Date:</b>	22-Mar-2016
<b>Name of Individual or Team:</b>	ALTRAD
<b>Details of safety observation:</b>	ALTRAD Since the week safety password is "Prevent the Fall" I focused my safety round observation on works at heights / excavations fencing. In particular I spent some time to observe an ALTRAD work crew installing a new scaffolding. The outcome has been positive as they performed the activity following all safety procedure on work at heights and adopting all necessary PPE.
<b>Immediate action taken:</b>	No action but compliments to the crew.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No