

<b>Observation Number:</b>	201810248
<b>Originator:</b>	
<b>Date Created:</b>	18-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Dukes Town Road, Tredegar
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Richard Date
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	05-Mar-2018
<b>Observation Time:</b>	08:15
<b>Observation Close Date:</b>	19-Jul-2018
<b>Details of safety observation:</b>	Snow plough pushed all barriers down over the weekend, due to the bad weather
<b>Immediate action taken:</b>	Team have made site safe and secure, and reported Monday morning.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Action to be taken:</b>	No LSR breach
<b>Supporting Information:</b>	
<b>Comments from OU Admin</b>	
<b>Closing Comments:</b>	No further action required