

<b>Observation Number:</b>	201815756
<b>Originator:</b>	
<b>Date Created:</b>	23-Oct-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	SPIN - CONTRAST MEDIA PLANT EXPANSION
<b>Service Line:</b>	SERC
<b>Site/Office Name:</b>	Spin- CMPE Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	richiesta pulizia e ordine nell'area greenfield al fine di eliminare il pericolo di inciampi o urti
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	sergi domenico
<b>Observer Email Address:</b>	domenico.sergi@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	23-Oct-2018
<b>Observation Time:</b>	10:30
<b>Observation Close Date:</b>	07-Nov-2018
<b>Observation Category:</b>	Work Environment Lighting & Noise
<b>Details of safety observation:</b>	Scarsa illuminazione generale alle prime ore del mattino e il fatto che utilizzano la greenfield come officinal per preparare I materiali per le alter zone brown ha reso l'area caotica
<b>Immediate action taken:</b>	L'impresa informata si attuava subito alla pulizia e al riordino delle attrezzature/materiale
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No