

Observation Number:	201810248
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Dukes Town Road, Tredegar
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	05-Mar-2018
Observation Time:	08:15
Observation Close Date:	19-Jul-2018
Details of safety observation:	Snow plough pushed all barriers down over the weekend, due to the bad weather
Immediate action taken:	Team have made site safe and secure, and reported Monday morning.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Action to be taken:	No LSR breach
Supporting Information:	
Comments from OU Admin	
Closing Comments:	No further action required