

Observation Number:	201912954
Originator:	
Date Created:	11-Jun-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Security Hut site entrance
Observation Type:	Unsafe Condition
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	3rd Party
Observation Date:	11-Jun-2019
Observation Time:	05:45
Observation Close Date:	14-Jun-2019
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)
Details of safety observation:	When waiting for lift from security office to site there is no where to shelter from inclement weather
Immediate action taken:	
Supporting Information:	
Feedback required?:	Yes
Comments from Reviewer	
Closing Comments:	Sheltered walkways to be provided once permanent car park is installed off site.