

| | |
|---|--|
| Observation Number: | 201808431 |
| Originator: | |
| Date Created: | 24-Jun-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Woodfield St Swansea |
| Observation Type: | Unsafe Act |
| Observer Name: | Christopher John |
| Observer Email Address: | trevor.clark@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 09-Jan-2018 |
| Observation Time: | 10:45 |
| Observation Close Date: | 27-Jun-2018 |
| Details of safety observation: | ISL Intervention Team parked their vehicle on a busy main rd on a bend , when they got out of the vehicle they realised the lorry they had parked was parked in an unsafe position |
| Immediate action taken: | The driver got back in the vehicle and moved the lorry to a safe place |
| Supporting Information: | |
| Feedback required?: | No |