

Observation Number:	201809729
Originator:	
Date Created:	11-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Heol Cadifor Swansea
Observation Type:	Unsafe Condition
Observer Name:	Adam Evans
Observer Email Address:	steve.edwards@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	01-Feb-2018
Observation Time:	11:45
Observation Close Date:	16-Jul-2018
Details of safety observation:	2 incidents regarding the new Sperryn emergency control valves the main tap competed and tightened by the team you would have to use a spanner with force release , but there seems to be a quarter of an inch of play in it
Immediate action taken:	Rang in a heart observation and will arrange for the materials to be investigated by Thomas James . Adam Evans has also taken a video and he will pass this on
Supporting Information:	
Feedback required?:	No