

Observation Number:	201810281
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Wrexham Road Johnstown
Observation Type:	Unsafe Condition
Observer Name:	Adrian Degg
Observer Email Address:	paul.astley@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	11-May-2018
Observation Time:	12:15
Observation Close Date:	12-Sep-2018
Details of safety observation:	Unsafe condition, Deep excavation with shuttering, props and wailers in use as per Design 3 (Closed), however wailers in use were 225mm x 75mm, whereas for a 2m deep excavation should be either 175mm x 100mm or 225mm x 150mm.
Immediate action taken:	Action, coached team, had them backfill excavation until correct wailers on site and installed.
Supporting Information:	
Feedback required?:	No