

Observation Number:	202029319
Originator:	
Date Created:	17-Jun-2020
Business Unit:	Asset Solutions Americas
Business Group:	Capital Projects Power Process & Energy
Project/Office:	Lincoln County CT Project
Service Line:	EPC Industrial
Site/Office Name:	Lincoln County CT Project
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Fuel Oil Tank
Observation Type:	Safe Behaviour
Observer Name:	Shanice Kirkland
Observer Email Address:	katie.schroeder2@woodplc.com
Stakeholder:	Wood
Observation Date:	06-Jun-2020
Observation Time:	09:30
Observation Close Date:	17-Jun-2020
Observation Category:	Contractor Site safety Safety awareness & behaviour
Name of Individual or Team:	Pipe Crew
Details of safety observation:	Before starting a pipe test the crew makes sure there is no one in the area and that the barricade is properly established.
Immediate action taken:	
Supporting Information:	
Feedback required?:	No