

Observation Number:	201804453
Originator:	
Date Created:	06-Apr-2018
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	SPIN - CONTRAST MEDIA PLANT EXPANSION
Sub Business Group:	Europe & Africa
Site/Office Name:	Spin- CMPE Site
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Durante lavorazione in torre B7 piano 3 accanto a ringhiera di balconata, si piazzavano travi in legno vicino al bordo della balconata, su trabattello correttamente installato, dovutamente segregato e segnalato.
Observation Type:	Unsafe Condition
Observer Name:	sergi domenico
Observer Email Address:	domenico.sergi@woodplc.com
Stakeholder:	Wood
Observation Date:	06-Apr-2018
Observation Time:	11:45
Observation Close Date:	06-Jun-2018
Details of safety observation:	Area sottostante di libero accesso anche se limitato alle maestranze di progetto tutte impregnate al momento dell'osservazione al piano 3. Richiesto di delimitare l'area al piano terra di possibile caduta materiale.
Immediate action taken:	Area evidenziata e interdetta al passaggio mezzo fettucciato e cartelli
Supporting Information:	
Feedback required?:	No