

Observation Number:	201808428
Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Bracken way Drybrook Glos
Observation Type:	Unsafe Condition
Observer Name:	Mark Green
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	17-Jan-2018
Observation Time:	08:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	All signs and barriers were down thrown around the site and not covering the patch .Please note NOT A REINSTATEMENT JOB (WWU)
Immediate action taken:	Mark Green made the site safe and secure and put up the correct signage e.g arrow signs
Supporting Information:	
Feedback required?:	No