

| | |
|---|---|
| Observation Number: | 201808471 |
| Originator: | |
| Date Created: | 25-Jun-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Sub Business Group: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Meas Mor Yard Glos |
| Observation Type: | Unsafe Condition |
| Observer Name: | Mickey Wright |
| Observer Email Address: | trevor.clark@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 12-Jan-2018 |
| Observation Time: | 13:15 |
| Observation Close Date: | 27-Jun-2018 |
| Details of safety observation: | Complete Utilities :Foot wacker leaking petrol |
| Immediate action taken: | Excahanged the footwacker and sent the other one to be repaired |
| Supporting Information: | |
| Feedback required?: | No |