

<b>Observation Number:</b>	201926741
<b>Originator:</b>	
<b>Date Created:</b>	06-Oct-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Kemerton Project
<b>Sub Business Group:</b>	Mining & Minerals
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	SMP tank assembly area
<b>Observation Type:</b>	Safe Condition
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	03-Oct-2019
<b>Observation Time:</b>	12:45
<b>Observation Close Date:</b>	07-Oct-2019
<b>Observation Category:</b>	Integrity Management Competence
<b>Details of safety observation:</b>	Lifting of roof tank section onto middle section, all procedures followed , lift study in place pre-team talk prior to lift all areas correctly barricaded a task well done.
<b>Immediate action taken:</b>	Congratulated team
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No