

<b>Observation Number:</b>	201810600
<b>Originator:</b>	
<b>Date Created:</b>	24-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Chestnut Way, Gurnos
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Richard Date
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	10-Jul-2018
<b>Observation Time:</b>	13:15
<b>Observation Close Date:</b>	
<b>Details of safety observation:</b>	When the team were digging a connection hole , they un covered a cable not on the plans , the cable was in poor condition
<b>Immediate action taken:</b>	T/L contact WPD , they have been out to site they though the cable was dead when they split it , the cable was live it was a St Light Column.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Cancel Comments:</b>	Near miss cable strike - should've been investigated fully