

|   |   |
|---|---|
| <b>Observation Number:</b>  | 201808469   |
| <b>Originator:</b>  |   |
| <b>Date Created:</b>  | 25-Jun-2018   |
| <b>Business Unit:</b>   | AS EAAA   |
| <b>Business Group:</b>  | Operations Services Europe & Africa   |
| <b>Project/Office:</b>  | Western Gas Alliance  |
| <b>Service Line:</b>  | Transmission & Distribution   |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6  |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related  |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Woodland Rd Croesyceilog Cwmbran  |
| <b>Observation Type:</b>  | Unsafe Act  |
| <b>Observer Name:</b>   | John Ross   |
| <b>Observer Email Address:</b>                                    | trevor.clark@wwutilities.co.uk  |
| <b>Stakeholder:</b>   | Wood  |
| <b>Observation Date:</b>  | 19-Jan-2018   |
| <b>Observation Time:</b>  | 12:30   |
| <b>Observation Close Date:</b>                                    | 27-Jun-2018   |
| <b>Details of safety observation:</b>                             | ISL Intervention :Team member left a jack hammer on the side of a walk way which was noticed by T/L straight away |
| <b>Immediate action taken:</b>                                    | T/L pulled team member to one side and explained the trip hazard for the safety of the public                     |
| <b>Supporting Information:</b>                                    |   |
| <b>Feedback required?:</b>  | No  |