

Observation Number:	201927117
Originator:	
Date Created:	10-Oct-2019
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	Kemerton Project
Sub Business Group:	Mining & Minerals
Site/Office Name:	Kemerton Project Site
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Lifting of tank sections into position SMP assembly area
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	10-Oct-2019
Observation Time:	08:15
Observation Close Date:	10-Oct-2019
Observation Category:	Contractor Site safety Safety planning
Name of Individual or Team:	Civmec SMP team
Details of safety observation:	Observed group lifting two tank section onto one tank section to complete fit up and weld, Checked lift stud, JHA & confined space all was correct and in place, group had team talk prior to lift so all channels of communications followed area totally barricaded from other work groups so no interface issues .
Immediate action taken:	Congratulated team on task well done.
Supporting Information:	
Feedback required?:	No